

Your satisfaction with your Volvo and the Volvo organization is very important to us. We are committed to ongoing product improvements; therefore, we have launched Active Service Campaign A10140 Antenna Cover.

The Reason for Active Service Campaign A10140:

Volvo Car USA LLC, on behalf of Volvo Car Corporation, has decided to launch Active Service Campaign A10140 on certain Model Year 2021 and 2022 90 Series, XC60 and XC40 vehicles with Google built-in.

Volvo Cars quality investigations have identified that there's a risk of a gap between the car body and the antenna cover. This may lead to noise and water intrusion and if not addressed there may be a risk that water damages the TCAM which over time could potentially, in rare cases, result in loss of connectivity and a message in DIM.



Your authorized Volvo retailer will inspect the gap between the antenna cover and car body. If necessary, Volvo Cars will refit the antenna cover.

Your satisfaction with your Volvo and the Volvo organization is very important to us. We are committed to ongoing product improvements; therefore, we have launched Active Service Campaign A10140 Antenna Cover.

The Reason for Active Service Campaign A10140:

Volvo Car USA LLC, on behalf of Volvo Car Corporation, has decided to launch Active Service Campaign A10140 on certain Model Year 2021 and 2022 90 Series, XC60 and XC40 vehicles with Google built-in.

Volvo Cars quality investigations have identified that there's a risk of a gap between the car body and the antenna cover. This may lead to noise and water intrusion and if not addressed there may be a risk that water damages the TCAM which over time could potentially, in rare cases, result in loss of connectivity and a message in DIM.



Your authorized Volvo retailer will inspect the gap between the antenna cover and car body. If necessary, Volvo Cars will refit the antenna cover.