

Delivery 1/23/2021 12:40:46 AM

Control Module - Diagnostic Trouble Code	Status
ABS	No fault found
CCM-0013 Damper motor air distribution Blocked	DTC is found active.
CCM-0081 Damper motor temperature Signal missing	DTC is found active.
CCM-0085 30-power supply Power supply missing	DTC is found active.
CCM-0012 Damper motor temperature Blocked	DTC is found not active.
CCM-0007 Position sensor damper motor temperature Signal too high	DTC is found not active.
CEM-0027 Battery voltage Signal too low	DTC is found not active.
DIM	No fault found
DSA-212 Brake light switch Faulty signal	DTC is found not active.
DSA-121 DSA switch Signal too low	DTC is found not active.
ECM-44 Missfire, Emmission level - Faulty signal	DTC is found active.
ECM-45 Missfire, Emmission level - Faulty signal	DTC is found active.
ECM-4D Misfire which damages catalytic converter - Faulty signal	DTC is found active.
ECM-61 Reset valve, camshaft - Faulty signal	DTC is found active.
ECM-91 Torque reduction - Faulty signal	DTC is found active.
IMM-38	DTC is found not active.
SRS-0137 Right SIPS bag Faulty signal	DTC is found not active.
SRS-013D Left SIPS bag Faulty signal	DTC is found not active.
SRS-0154 Seat belt buckle, driver Signal too low	DTC is found not active.
SRS-0158 Seat belt buckle, passenger Signal too low	DTC is found not active.
TCM	No fault found
VGLA-311 Siren Faulty signal	DTC is found active.