

S60 (-09),2003,B5244S,YV1RS61T132262691

Initial State 12/23/2016 11:42:48 AM

Control Module - Diagnostic Trouble Code	Status
AUM	No fault found
BCM	No fault found
CCM	No fault found
CEM	No fault found
DDM	No fault found
DIM-0003 SRS Faulty circuit	DTC is found not active.
DIM-0005 Red warning lamp Faulty circuit	DTC is found not active.
DIM-0006 Orange warning lamp Faulty circuit	DTC is found not active.
ECM-990F Torque monitoring	DTC is found active.
PDM	No fault found
PSM	No fault found
REM	No fault found
SRS-00D4 SRS lamp Faulty signal	DTC is found active.
SWM-0003 High beam flash Activated too long	DTC is found not active.
TCM	No fault found
UEM	No fault found