




Operation number: 88210-2

Inner rear view mirror


Removal

Note!

Removal steps in this procedure may contain installation details.




Installation



Caution!


Take extra care when handling the component.

Vehicles with Proximity Warning Camera



Caution!


Take extra care when handling the component.



Caution!

Take extra care when handling the component.

All vehicles



Caution!

Only turn at the base of the mirror.

To install, reverse the removal procedure.

Order and download software according to: [30774384](#)

Vehicles with Electronic Compass

